

FIG.1




FIG.2





FIG. 3



09766133-011901

FIG. 4





FIG.5

OPTICAL DISK 85



09/63/01/90

FIG.6





FIG.7



0966132-011901

FIG.8






FIG.9






FIG. 9

FIG. 10



09766432, 011901

FIG.11



0976133-011001

FIG.12A




FIG.12B




FIG.12C




FIG.12D





FIG.12E



09766132 011501

FIG.13A




FIG.13B






FIG.13C



09/66133-014901

FIG.14



09766132-011901

FIG.15A

MOVING DIRECTION OF OBJECT




FIG.15B




FIG.16A





FIG.16B



09766133-011901